

# Command:MOVE (M)

MS2000 or RM2000 syntax

<b>Shortcut</b>	M
<b>Format</b>	MOVE [Axis]=[units 1/10 microns]...
<b>Units</b>	1/10 microns

Tiger syntax

<b>Shortcut</b>	M
<b>Format</b>	MOVE [Axis]=[units 1/10 microns]...
<b>Units</b>	1/10 microns
<b>Type</b>	Axis-Specific

Move one or more axis motors to an absolute position. Uses the scaling of the "["UM" command](#), i.e. usually 10ths of microns for stages. If no position is specified, 0 (the origin) is assumed.

For devices with **CLOCKED POSITIONS** (e.g. turrets and filter sliders), the position is an integer value between one and the number of positions. Note that ASI filter wheels have a separate command set described in the [filter wheel documentation](#).

A positive reply of :A is sent back when the command is received correctly. Reception of the reply does not mean the end of execution, and the command STATUS can be used to determine if the move has been completed.

## Example

Send a command to move to a position and send a command to move to the origin.

```
M X=1234 Y=4321
:A
M X Y
:A
```

The controller will move the X-axis to position 123.4 microns from the origin using the maximum set speed (see SPEED). Simultaneously, it will move the Y-axis to position 432.1 microns, and the Z-axis to the zero (0) position.

During this movement, the Joystick and Encoder inputs will be locked-out and cannot alter the target positions entered. The motors will stop when they have reached their target or when their limit switch is encountered. To stop the motors during a serial MOVE command, use the HALT ( \ ) command.



**Note:** For Rotary and Theta stages the unit multiplier (UM) is in thousandths of a degree.

[commands](#), [tiger](#), [ms2000](#), [SPEED](#), [VECTOR](#)

From:

<http://www.asiimaging.com/docs/> - **Applied Scientific Instrumentation**



Permanent link:

<http://www.asiimaging.com/docs/commands/move>

Last update: **2025/03/19 19:03**