Command:ZF

Not implemented. This command was known as ZFLOCK (ZF). Command not present on MS2000 and unused on Tiger. Instead we use SLAVE_F_TO_Z module that doesn't have the ability to be controlled via a command, though if needed the ability to turn on and off or change which axis is the master then it could be added.

deprecated, zflock

From:
https://www.asiimaging.com/docs/ - **Applied Scientific Instrumentation**

Permanent link:
https://www.asiimaging.com/docs/commands/zflock

Last update: **2024/06/25 05:02**