

Command:UNITS (UN)

Shortcut	UN
Format	UNITS
Remembered	Using SS Z

Toggles between millimeters and inches shown on the LCD display when DIP Switch 2 is down.

Reply

If there are no errors, a positive reply of :A is returned.

Unit Multiplier

To change the Unit Multiplier use the [Command:UM](#) command.

[commands](#), [ms2000](#)

From:
<https://asiimaging.com/docs/> - **Applied Scientific Instrumentation**

Permanent link:
<https://asiimaging.com/docs/commands/units>

Last update: **2024/12/08 22:49**

